

Job Opening

If interested, please submit an application or resume to humanresources@ontargetservices.com or fax to (207) 588-4525 or mail to On Target Utility Services, Human Resources, 617 Water Street, Gardiner, ME 04345. **To be considered, submissions must include applicant name, phone contact and position specific "Code" (below).**

LOCATION: On Target Utility Services – Portland, Maine
POSITION: Fiber Optic Tester/Splicer
CODE: FOTS20-10
REPORTS TO: Project Manager
SUBMISSION DEADLINE: July 26, 2010

Essential Functions

- Responsible for the testing of fiber optic cable; along with displaying and interpreting results for the purpose of analyzing and documenting fiber optic links. Ability to operate the following devices:
 - OTDR (Optical Time-Domain Reflectometer) - measures end-to-end loss, point losses such as splices, connectors and fiber breaks.
 - Power Meter & Light Source - displays system loss over the fiber and both end connectors.
- Responsible for successfully joining optical fibers through the use of a fusion splicer. Attaining a low loss splice through a proficient cleave (cut) and splice is required.
- Ability to safely operate a bucket van.
- Travel extensively in and out-of-state.
- Must be available for weekend, night shifts, on call duty, emergency calls or on demand appointments as required or directed by Company representatives or answering service; responding as required and/or directed.
- Must be able to work a flexible schedule in order to meet customer demands/schedule.
- Must have valid driver's license.
- Perform other duties as assigned.

Knowledge/Education/Skills/Experience

- Ability to work independently with little or no supervision.
- Must be deadline driven with the ability to work as required to meet client's needs.
- Strong organizational skills required.
- Detail oriented along with a high level of accuracy is required.
- Maintain professional appearance of self and vehicle/equipment
- Personal computer knowledge is desirable.
- Knowledge of GN Nettek (OTDR) and Alcoa Fujikura (Fusion Splicers) equipment is a plus.
- Maintain knowledge of technological changes through continuing education, training and trade articles.
- Two (2) year college degree or 2-4 years of related experience.
- Must be able to use all types of common hand tools and splicing tools of the trade.
- Has thorough knowledge of the Company's operating standards, policies, directives and safety instructions pertaining to the work assignments.

Physical Requirements

- Must be able to climb utility poles and work out of an aerial lift devise.
- Must be able to lift 100 lbs. on an occasional basis and up to 50 lbs. on a frequent basis.
- Must be able to stand, walk and work on uneven ground for the full workday.
- Must be able to sit for long periods of time.
- Must have good eyesight and hearing capabilities.
- Must work outside in all types of weather conditions.